



Kirby Morgan Dive Systems, Inc.®

1430 Jason Way, Santa Maria, California 93455

Phone: 805/928-7772 Fax: 805/928-0342

www.kirbymorgan.com e-mail: kmddsi@kirbymorgan.com

Bulletin #1 of 2017. October 5, 2017

Maintenance & Repair Bulletin

**Band Mask Hood Molded Face Seals now
available separately / Sold as Kits**

NEW Replacement molded face seals:

| Part Number | Description |
|--------------------|--|
| 525-725 | KMB Molded Face Seal Replacement Kit (S) |
| 525-726 | KMB Molded Face Seal Replacement Kit (M) |
| 525-727 | KMB Molded Face Seal Replacement Kit (L) |

Products Affected:

Band Mask® 18 with Molded Face Seal Hood installed

Band Mask® 28 with Molded Face Seal Hood installed

Hoods with Molded Face Seals:

525-730 KMB-28 (S/M) Hood (w/S) Molded Face Seal

525-731 KMB-28 (S/M) Hood (w/M) Molded Face Seal

525-732 KMB-28 (L) Hood (w/M) Molded Face Seal

525-733 KMB-28 (L) Hood (w/L) Molded Face Seal

525-734 KMB-18 (S/M) Hood (w/S) Molded Face Seal

525-735 KMB-18 (S/M) Hood (w/M) Molded Face Seal

525-736 KMB-18 (L) Hood (w/M) Molded Face Seal

525-737 KMB-18 (L) Hood (w/L) Molded Face Seal

Molded face seals can now be purchased separately.

NOT COMPATIBLE WITH STANDARD 510-712 HOODS

Molded face seals are NOT compatible with standard P/N 510-712 KMB hood assembly. That is, the standard foam face seal cannot be changed out for a molded face seal.

Kits Include: One face seal (small, medium or large) and instruction sheet.

Please contact your KMDDSI dealer or e-mail sales@kirbymorgan.com for more information.

